

# 800 Stain Remover

Sure Klean® 800 Stain Remover is a specialty masonry cleaning product that effectively removes green vanadium stains commonly found in buff or white brick. 800 Stain Remover also removes straw stains, acid burns and other metallic discolorations from most masonry surfaces.

Many staining conditions are created by excessive moisture in the walls. To avoid this, protect open wall cavities from rainwater during construction and correct any structural problems that allow water to enter the walls.

#### **ADVANTAGES**

- Removes tough metallic stains quickly and easily.
- Recommended for surfaces containing colored mortar.
- Water rinsable.

#### Limitations

- Not recommended for use on polished surfaces.
- Will not correct damage caused by improper use of hydrofluoric acid cleaning solutions.
- Acidic contents and fumes may damage non masonry and acid-sensitive surfaces.

## REGULATORY COMPLIANCE

#### **VOC Compliance**

Sure Klean® 800 Stain Remover is compliant with all national, state and district VOC regulations.

## TYPICAL TECHNICAL DATA

FORM	Clear, colorless liquid		
SPECIFIC GRAVITY	1.056		
pН	1.4 in concentrate		
WT/GAL	8.78 lbs		
ACTIVE CONTENT	not applicable		
TOTAL SOLIDS	not applicable		
VOC CONTENT	not applicable		
FLASH POINT	not applicable		
FREEZE POINT	not applicable		
SHELF LIFE	3 years in tightly sealed, unopened container		

# SAFETY INFORMATION

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job site controls during application and handling.

24-Hour Emergency Information: INFOTRAC at 800-535-5053



# **Product Data Sheet Sure Klean® 800 Stain Remover**

## **PREPARATION**

Sure Klean® 800 Stain Remover is corrosive, etches glass and architectural aluminum and is harmful to wood, painted surfaces and foliage. Beware of wind drift. Fumes will also cause damage. Maintain enough ventilation to avoid buildup of potentially damaging fumes.

Protect people, vehicles, property, plants, metal, all non masonry and acid-sensitive surfaces from contact with cleaner, rinse residue, fumes and wind drift. Protect and/or divert auto and pedestrian traffic.

Clean masonry before installing windows, doors, finished flooring, metal fixtures, hardware, light fixtures, roofing materials and other non masonry items. If already installed, protect with polyethylene. Sure Klean® Strippable Masking is appropriate for use with this product to protect windows.

All caulking and sealant materials should be in place and thoroughly cured before cleaning.

Recommended for these substrates. Always test.
Coverage is in sq.ft./m. per gallon of concentrate.

Substrate	Type	Use?	Coverage
Architectural Concrete Block	Burnished	no	-
	Smooth	no	N/A
	Split-faced	no	
	Ribbed	no	
Concrete	Brick	no	
	Tile	no	
	Precast Panels	no	N/A
	Pavers	no	
	Cast-in-place	no	
Fired Clay*	Brick	yes	
	Tile	yes	100–200 sq.ft.
	Terra Cotta (unglazed)	yes	9–19 sq.m.
	Pavers	yes	
Marble, Travertine, Limestone	Polished	no	N/A
	Unpolished	no	N/A
Granite	Polished	no	N/A
	Unpolished	yes	100–200 sq.ft. 9–19 sq.m.
Sandstone	Unpolished	yes	100–200 sq.ft.
			9–19 sq.m.
Slate	Unpolished	yes	100–200 sq.ft.
			9–19 sq.m.

\*Repeated application may damage surfaces.

Always test to ensure desired results. Coverage estimates depend on surface texture and porosity.

Avoid exposing building occupants to fumes. On occupied buildings, cover all windows, air intakes and exterior air conditioning vents. Shut down air handling equipment during cleaning and until surfaces are thoroughly dry. Use fans and supplemental ventilation when applying on interior surfaces. Maintain ventilation until surfaces are thoroughly dry. Fumes attack glass, metal and all other acid-sensitive surfaces.

Before removing metallic stains (vanadium), the masonry should be thoroughly dry to reduce recurrence of stains after cleaning.

#### **Surface and Air Temperature**

For best results, clean when air and masonry surface temperatures are 40° F (4° C) or above. Cleaning when temperatures are below freezing or will be overnight may harm masonry. If freezing conditions have existed, let the masonry thaw before cleaning.

#### **Equipment**

Apply with low-pressure (50 psi max) spray or densely-packed, soft-fibered masonry washing brush. Fit equipment with acid-resistant hoses and gaskets to avoid discoloration.

Rinse with enough water and pressure to flush spent cleaner and dissolved soiling from the masonry surface and surface pores without damage. Inadequate rinsing leaves residues which may stain the cleaned surface.

Masonry-washing equipment generating 400–1000 psi with a water flow rate of 6–8 gallons per minute is the best water/pressure combination for rinsing porous masonry. Use a 15–45° fan spray tip. Heated water (150–180° F; 65–82° C) may improve cleaning efficiency. Use adjustable equipment for reducing water flow-rates and rinsing pressure as needed for sensitive surfaces.

Rinsing pressures greater than 1000 psi and fan spray tips smaller than 15° may permanently damage sensitive masonry. Water flow-rates less than 6 gallons per minute may reduce cleaning productivity and contribute to uneven cleaning results.

#### **Storage and Handling**

Transport and store in a cool, dry place with adequate ventilation. Always seal container after dispensing. Do not alter or mix with other chemicals. Published shelf life assumes upright storage of factory-sealed containers in a dry place. Maintain temperature of 45–100° F (7–38° C). Do not double stack pallets. Dispose of unused product and container in accordance with local, state and federal regulations.



# Product Data Sheet Sure Klean® 800 Stain Remover

#### **APPLICATION**

Read "Preparation" and the Safety Data Sheet before use.

ALWAYS TEST a small area (minimum 4-ft x 4-ft) of each surface to confirm suitability and desired results before beginning overall application. Test each type of masonry and each type of stain. Test with the same equipment, recommended surface preparation and application procedures planned for general application. Let test area dry 3–7 days before inspection and approval. Make the test panel available for comparison throughout the cleaning project.

#### **Dilution**

Use in concentrate for most applications. Testing indicates if 800 Stain Remover may be diluted with equal parts water.

Always pour COLD water into empty bucket first, then carefully add product. Never use hot water. Handle in polypropylene buckets only. Acidic materials and fumes attack metal.

#### **Typical Coverage Rates**

Reference the substrate chart on page 2. The coverage rate chart assumes an average coverage rate of 100 square feet per gallon of prepared cleaner.

When calculating the volume of cleaner required for porous, textured surfaces, assume 50 square feet per gallon of prepared cleaner.

For dense, smooth surfaces, assume up to 150 square feet per gallon of prepared cleaner.

## **Application Instructions**

#### Exterior Surfaces

- 1. Working from the bottom to the top, prewet the masonry surface with clean water.
- 2. Apply directly to the masonry surface from the bottom of the work area to the top.

- 3. Let the cleaner stay on the surface for 3–5 minutes or until stains are gone. If treated surfaces are left unattended, keep people away from cleaner.
  - *NOTE*: Do not let cleaner dry into the surface. If surface begins to dry in less than 5 minutes, water-rinse and reapply cleaner.
- 4. Working from the bottom of the work area to the top, reapply cleaner and rinse with fresh water. Thorough rinsing gets all residues off the surface. Older, more delicate masonry may require less water pressure to avoid damage. Avoid multiple applications. If pressure rinsing equipment is not available, rinse thoroughly with clean water, brushing the wall while rinsing.

#### Interior Surfaces

Test and follow cleaning procedure for exterior surfaces. Rinse thoroughly with fresh water using a sponge or soft-fibered brush.

If conditions do not allow enough water for complete rinsing, use a neutralizing rinse following this procedure:

- 1. Rinse with clear water.
- 2. Apply neutralizing rinse of 2 ounces baking soda to 1 gallon water.
- 3. Saturate. Leave solution on the surface 3–5 minutes.
- 4. Apply final rinse of clear water.

#### Cleanu

Clean tools and equipment using fresh water.

## WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions

# **BEST PRACTICES**

Before removing metallic stains (vanadium), the masonry should be thoroughly dry to reduce recurrence of stains after cleaning.

Rinse with enough water and pressure to flush spent cleaner and dissolved soiling from the masonry surface and surface pores without damage. Inadequate rinsing leaves residues which may stain the cleaned surface.

Always pour COLD water into empty bucket first, then carefully add product. Never use hot water. Handle in polypropylene buckets only. Acidic materials and fumes attack metal.

Never go it alone. For problems or questions, contact your local PROSOCO distributor or field representative. Or call PROSOCO technical Customer Care toll-free at 800-255-4255.



## Product Data Sheet Sure Klean® 800 Stain Remover

and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

PROSOCO, Inc. warrants this product to be free from defects. Where permitted by law, PROSOCO makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose. The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. PROSOCO's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of this product absolves PROSOCO from any other liability, from whatever source, including liability for incidental, consequential or resultant damages

whether due to breach of warranty, negligence or strict liability. This warranty may not be modified or extended by representatives of PROSOCO, its distributors or dealers.

#### **CUSTOMER CARE**

Factory personnel are available for product, environment and job-safety assistance with no obligation. Call 800-255-4255 and ask for Customer Care – technical support.

Factory-trained representatives are established in principal cities throughout the continental United States. Call Customer Care at 800-255-4255, or visit our web site at www.prosoco.com, for the name of the PROSOCO representative in your area.